

NOTICE:

If Mil light comes on after change of the valve, and the diagnostic tool gives the information, "the by-pass valve is blocked" you will need to have the vehicle software updated at an OE dealer.