



Fig. 1: New Version

Old Version



NOTE

The damper mount on front axle was replaced on the BMW models E36 and Z3. In addition to the visual difference, a position pin is located at the upper attachment surface. This pin is needed only in the Z4 model. Therefore, it **must** always be removed in the models **E36 and Z3**.



NOTE

Unscrew the position pin to remove it.
If the pin is not removed in the models E36 and Z3 fastening is impossible.