

SKF Product Information

VKM 64075 – OE/SKF Disegno tenditore organi ausiliari



Mazda 3, 6, CX-5 1.5, 2.0, 2.0 AWD, 2.5



OE/SKF Disegno tenditore organi ausiliari



OE Nb: PE03-15-980A, PE03-15-980B (Gruppo completo)



Due rondelle presenti nel kit SKF

Il tenditore ausiliario OE ha due diversi disegni della staffa, per tale ragione il tenditore SKF VKM 64075 (puleggia) presenta due rondelle in modo da poter essere usato per entrambi i disegni della staffa:

- Per la staffa disegno 1, le due rondelle devono essere montate in entrambi i lati della puleggia.
- Per la staffa disegno 2, soltanto una rondella deve essere montata sulla testa del bullone della puleggia.



Tenditore staffa disegno 1



Tenditore staffa disegno 2

Disegni diversi



Due rondelle da montare



Una rondella da montare sulla testa del bullone della puleggia

Rondell
a



[Click here to watch SKF technical videos on Youtube!](#)

© SKF is a registered trademark of the SKF Group.

© SKF Group 2016

The contents of this publication are the copyright of the publisher and may not be reproduced (even extracts) unless written permission is granted. Every care has been taken to ensure the accuracy of the information contained in this publication but no liability can be accepted for any loss or damage whether direct, indirect or consequential arising out of the use of the information contained herein.

March 2016

