



**Kundeninformation Mintex****ENGLISH VERSION ON PAGE 2****MDB2418 / MDB3106 → WVA 23312**

Aufgrund der Ersetzungen die im OES Bereich bei BMW erfolgt sind, sind einige Anpassungen bei den Artikeln MDB2418 und MDB3106 notwendig. Für die M-Modelle der 1er (E82) und 3er (E90-E93) Serie wird weiterhin MDB2418 verwendet. Alle anderen Modelle werden nun durch MDB3106 abgedeckt. MDB3106 ist somit auch rückwirkend für alle verknüpften Fahrzeuge einsetzbar.

BMW M-Modelle 1er (E82) und 3er (E90-E93) Serie:

**MDB2418**

BMW 5er (E60,E61), 6er (E63,E64) und 7er (E65,E66) Serie:

**MDB2418 → MDB3106****Unterschied ist die fehlende Haltefeder auf dem faustseitigem Belag (23347 vs. 23313)**


**Customer information Mintex**

**MDB2418 / MDB3106 ➔ WVA 23312**

Due to changes on OES side of BMW some amendment need to be done for references MDB2418 and MDB3106. For M-models of the BMW 1-Series (E82) and 3-Series (E90-E93) you can keep using MDB2418. All other vehicles, which used to be covered by MDB2418, will now be covered by MDB3106. Therefore MDB3106 is also applicable retrospectively for all other linked vehicles.


BMW M-Models of 1-Series (E82) and 3-Series (E90-E93):

**MDB2418**



BMW 5-Series (E60,E61), 6-Series (E63,E64) and 7-Series (E65,E66) Serie:

**MDB2418 ➔ MDB3106**



**Difference between both is the missing spring on the finger side pad (23347 vs. 23313)**