

febi

Tip



Drive pedal broken? You certainly know that from customers who bring a Mercedes Sprinter to your workshop. Also in this case, febi offers a cost-effective alternative, e.g. with the

Rep. kit drive pedal for all Mercedes Sprinter (except from CDI engines)

febi no. 18540 · ref. no. 9013000304

Although it is possible to drive the car with a broken drive pedal the driver loses every sense of touch for the actuation of the pedal. To ensure the safety of your customer you should replace the drive pedal in any case.

So why not use a spare part with OE quality that is even more cost-effective than an OE part?

By the way: The febi product range includes more than 800 parts for a proper repair only for the Mercedes Sprinter.

Please ask your febi partner for spare parts by febi bilstein. You will also find all spare parts at www.febi.com.

Valid as of 08/2005

www.febi.com

Ferdinand Bilstein GmbH + Co. KG · Wilhelmstr. 47 · 58256 Ennepetal
Fon +49 2333 911-0 · Fax +49 2333 911-444 · info@febi.com

bilstein group

