

# SERVICE INFO



## Design change affecting deflecting pulley 532 0504 10

### Vehicle

**Manufacturers:** Chevrolet, Isuzu,  
Mazda, Opel, Vauxhall

### Models:

**Chevrolet:** Astra, Corsa  
**Isuzu:** Gemini  
**Mazda:** 323 S  
**Opel:** Astra F, Astra G, Astra H,  
Combo, Corsa A, Corsa  
B, Corsa C, Corsa D,  
Kadett E, Meriva,  
Vectra A, Vectra B, Zafira  
**Vauxhall:** Astra Mk II, Astra Mk III,  
Astra Mk IV, Astra Mk V,  
Astra Mk VI, Cavalier  
Mk III, Combo, Corsa,  
Corsa Mk II, Corsa Mk III,  
Meriva, Nova, Vectra,  
Zafira Mk II

### Engines:


1.5 D, 1.5 TD, 1.6 TD,  
1.7 D, 1.7 Di, 1.7 DTi,  
1.7 CDTi

### OE Nos.:

**Isuzu:** 8-97309-459-1  
**Mazda:** Y701-12-730  
**Opel:** 6 36 928 / 97376296  
**Vauxhall:** 6 36 928 / 97376296

### Part No.:

532 0504 10



**Image 1:** 532 0504 10 – previous design



**Image 2:** 532 0504 10 – new design

As part of our continuous efforts to improve our products changes have been made to the deflection pulley, item no. 532 0504 10. This Service Information sheet shows the visual features of the previous (Image 1) and new (Image 2) version.

During the transitional phase, we may have mixed stocks of both types. Both versions meet the relevant technical specification and can be used without restrictions.



Note the specifications of the vehicle manufacturer!

Appropriate spare parts can be found in our on-line catalogue at [www.Schaeffler-Aftermarket.com](http://www.Schaeffler-Aftermarket.com) or in RepXpert at [www.RepXpert.com](http://www.RepXpert.com).

Issued 03.2010

**INA 0056**

Subject to technical changes

© 2010 Schaeffler Automotive Aftermarket

### For further information:

Phone: +44 (0) 14 32 264 264\*

Fax: +44 (0) 14 32 375 760

Info@LuK-AS.co.uk

[www.Schaeffler-Aftermarket.com](http://www.Schaeffler-Aftermarket.com)

\* Calls from within the UK 08457 001100

