

Fitting Guidelines

Direct Fit Oxygen/Lambda Sensor



This oxygen sensor differs from the original part fitted to a number of Toyota Yaris models, as it does not include a section of heat shield material and a number of clips used to fix the wire in place.

The sensor is a suitable direct replacement for these applications and has been sold in this form for a while, with no reported issues. The heat of the exhaust does not affect the sensor wire once it is located as per the original sensor and cable ties or other suitable fixings can be used in place of the original clips to ensure it is fixed in place correctly.