

Camshaft Tightening Procedure Procedimiento de Apriete de Árboles de Levas

93099200	MAKE MARCA	ENGINE MOTOR	CAMSHAFT PINION TIGHTENING APRIETE PIÑÓN ÁRBOL LEVAS	CAMSHAFT BEARING TIGHTENING APRIETE COJINETE DEL ÁRBOL
Kilos	LAND ROVER ROVER GROUP	15G - 21D - 22D 23D - 24D - 25D 15D-23D-24D-25D	6 Kpm	
Libras	LAND ROVER ROVER GROUP	15G - 21D - 22D 23D - 24D - 25D 15D-23D-24D-25D	43 lbft	

AJUSA IS NOT RESPONSIBLE FOR ANY UPGRADE AFTER THIS DOCUMENT HAD BEEN PRINTED. FOR MORE INFO, PLEASE VISIT OUR WEBSITE www.ajusa.es

AJUSA NO SE RESPONSABILIZA DE CUALQUIER ACTUALIZACIÓN POSTERIOR A LA IMPRESIÓN DE ESTE DOCUMENTO. PARA MAYOR INFORMACIÓN VISITE NUESTRA PAGINA WEB www.ajusa.es