

Camshaft Tightening Procedure Procedimiento de Apriete de Árboles de Levas

| 93105600 | MAKE MARCA | ENGINE MOTOR | CAMSHAFT PINION TIGHTENING APRIETE PIÑÓN ÁRBOL LEVAS | CAMSHAFT BEARING TIGHTENING APRIETE COJINETE DEL ÁRBOL |
|----------|---------------|-----------------|---|---|
| Kilos | HONDA | D16Z6/7 | 4 Kpm | M6 = 1.5 Kpm / M8 = 2.5 Kpm |
| Libras | HONDA | D16Z6/7 | 29 lbft | M6 = 11 lbft / M8 = 18 lbft |

AJUSA IS NOT RESPONSIBLE FOR ANY UPGRADE AFTER THIS DOCUMENT HAD BEEN PRINTED. FOR MORE INFO, PLEASE VISIT OUR WEBSITE www.ajusa.es

AJUSA NO SE RESPONSABILIZA DE CUALQUIER ACTUALIZACIÓN POSTERIOR A LA IMPRESIÓN DE ESTE DOCUMENTO. PARA MAYOR INFORMACIÓN VISITE NUESTRA PAGINA WEB www.ajusa.es