



INA Service Info



Tensioning arm 534 0610 10 replaces 534 0241 10

Visual differences

Manufacturer: Alfa, Cadillac, Fiat, Lancia, Opel, Saab, Suzuki, Vauxhall

Models:

Alfa: Brera, Giulietta, Mito, Spider, 159
 Cadillac: BLS
 Fiat: Bravo, Croma, Doblo, Ducato, Freemont, Punto, Linea, Sedici, Stilo
 Lancia: Delta, Musa
 Opel/Vauxhall: Astra, Combo, Signum, Vectra, Zafira
 Saab: 9-3, 9-5
 Suzuki: SX4

Engines: 1.6, 1.7, 1.9, 2.0

Part no.: 534 0241 10 (replaced)
 534 0610 10 (new)

For current listing refer to catalogue media



Figure 1: Old design



Figure 2: New design

As a result of continuous development of our products, the tensioning arm of the auxiliary system drive has been optimized for the engines listed. For this reason, the previous tensioning arm 534 0241 10 has been replaced by part no. 534 0610 10.

The pictures show the visual differences between the previous design and the new one.

The two designs differ in appearance only. They both meet the technical specifications and can be used without restriction.

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264
 Fax: +44 (0) 1432 375 760
 aftermarket.uk@schaeffler.com
 www.repxpert.co.uk

SCHAEFFLER
REP>XPERT