

Technical Advice

Head Surface Finish

Before fitting a replacement head gasket





April 2018



Incorrect

Ensure the cylinder head and engine block surfaces have been checked, ensuring level sealing surfaces.

Maximum values: Roughness <15µm & Distortion <0.03mm per 100mm

Head and block surface must be free from debris and corrosion, particularly around the cooling system passage ways.

The cylinder head bolt threads in the cylinder block must be cleaned with a thread tap and new head bolts used if specified.

<u>Do not</u> use any additional sealing compound.

All gaskets must be fitted dry.



Best Availability. Best Value. **Best Quality. Best Service.**

TB0010





faiauto.com

+44 (0) 1525 351800

