INF121_19 | Technical data are subject to change | March19

Blue Print ADH25501




to fit:

Rover 600 1996>1998 / Honda Accord 1990>2003, Odyssey 1994>2003, Prelude 1992>2000, Shuttle 1995>2001



BALANCE SHAFT LOCKING PIN SCREW

Blue Print's 'Locking Pin Screw' ADH25501 is required to allow correct alignment of the balancer shaft when replacing the timing and balancer shaft belts on many Honda models. The balancer shaft is driven by the crankshaft via a toothed belt that needs to be removed when replacing the timing belt, and is usually replaced at the same time.



- Access for the balancer shaft locking pin screw is via a blanking plug shown above.
- Remove the plug and insert the locking pin while carefully rotating the crankshaft until the pin and shaft are correctly aligned.
- Due to the offset nature of the slot in the balancer shaft, it is not possible to fit the pin 180 degrees out.

Failure to use the correct tools and adhere to the correct instructions could result in severe engine damage.

We recommend that you do not attempt timing belt replacement unless you have the full manufacturer's instructions for performing the maintenance/ repair.

For more technical information please visit: partsfinder.bilsteingroup.com